

■ CONVERSION TABLE

gauge ↔ *mil* ↔ *micron* ↔ *mm*



Gauge	Mil	Micron	MM
50	0.50	12.5	0.0125
60	0.60	15.0	0.015
75	0.75	19.0	0.019
100	1.00	25.0	0.025
120	1.20	30.0	0.03
160	1.60	40.0	0.04
180	1.80	45.0	0.045
200	2.00	50.0	0.05
300	3.00	75.0	0.075
400	4.00	100.0	0.1
430	4.30	107.5	0.1075
450	4.50	112.5	0.1125
500	5.00	125.0	0.125
600	6.00	150.0	0.15
700	7.00	175.0	0.175
800	8.00	200.0	0.2
900	9.00	225.0	0.225
1000	10.00	250.0	0.25